


Accelerometer

Connect the accelerometer using either the I²C or SPI method.



Gyroscope

Connect the rate and temp headers to the Analog Breakout as shown.

